



City Manager's Office
559/591-5904

Development Services
559/591-5906

Parks & Community Services
559/591-5940

City Attorney
559/734-6729

Public Works Services
559/591-5924

Fire/Ambulance Services
559/591-5931

Administrative Services
559/591-5900

Engineering Services
559/591-5906

Police Services
559/591-5911

IMPORTANT INFORMATION ABOUT YOUR DRINKING WATER SERVICE LINES

As mandated by the United States Environmental Protection Agency (U.S. EPA) Lead and Copper Rule Revisions, water systems are required to prepare and maintain a Lead Service Line (LSL) inventory, to identify lines that contain or possibly contain lead.

The purpose of the inventory is to identify the material utilized throughout the system, both the City responsible infrastructure within the public street and the customer responsible infrastructure that begins immediately beyond the water meter. The City of Dinuba is committed to delivering safe drinking water and we encourage customers to inspect your water connection.

The City of Dinuba has submitted its initial LSL inventory to the U.S. EPA, and which indicates that 50% of the connections did not include lead materials during construction. This initial step is followed with further verifications and LSL inventory maintenance and updates to continue to protect public health. The remaining accounts were listed as “unknown” service line material at this time, pending the City’s ongoing work with a consultant to identifying them.

As a City of Dinuba water customer, a notice will be sent to those service connections that were classified as “unknown”. This LSL inventory, and subsequent notice, is not a result of an emergency, but rather due to uncertain materials. In the past, various materials may have been used during construction of the system that may include lead or galvanized pipe. Lead Service Lines (LSL) or certain galvanized pipeline can potentially place you at risk for exposure to lead; therefore, the line will only need to be replaced if it is determined to be LSL or Galvanized Requiring Replacement (GRR).

The City of Dinuba has not encountered any lead service lines in the past, but we will be required to verify that our system does not contain them. The digital copy of the submitted inventory may be accessed by clicking on this link: <https://dinuba.org/images/2025/Service-Line-Inventory-Summary-2025.xlsx>